




Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.


## 


If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.






















⇒


в

А



							1 3995 1 SX F2
16	15	14	13	12	11	10	9 PAGE 114





	8	7	6	5	. ↓	4	З	2	1	
		I-NM 14 YEL 2-PM 14 WHT 4-VEL 5-NJ 14 WHT 5-NJ 14 WHT 7-FFW 14 YEL 9- FFW 5-FFW 14 YEL 9- FFW	NECTS TO ASH-COACH 2: D-15) © © 0 © © 0 PM NM JN	I 2V JACK JG JN I 4 YEL I4 WHT I4	COURTESY LAMP PM PJ I4 VEL	PORCH LA	MP POPCH//COURTES: LAMP SWITCH J J J J VJ PJ NM	Y LANP SWITT		<u>3995 I</u> D
▲			H H WIRE ASM- COACH WALLF	L-FFM 2-FFJ 2-FFJ NONE PLATE	FFH FFJ 2 WHT 2 WHT 2 CONNECTS TO DOOR AWNING	FFJ FFJ FFJ FFJ FFJ FFJ FFJ FFJ FFJ FFJ	FFF FFF	FFG C C C C C C C C C C C C C	02 P36L DO NOT SCALE DRAW WIRING DIAGRAM-BOD	
	8	7	6	5	t	4	З	2	энет 5 <sup>рат №</sup> 1399 1 РА	951 GE 117

D

 $\cap$ 

В

