




DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.



Winnebago

0 0 0 0 0 0 0 0 0 0

DFTR

CHKR

P.E.

M.E.

DSNR

ORIG. DATE

ALL DIMENSIONS ARE IN MILLIMETERS

FIRST USED

UNSPECIFIED TOLERANCES ARE:

THIRD ANGLE PROJECTION

MATERIAL:

DO NOT SCALE DRAWING

TITLE:

WIRING DIAGRAM-BODY, 110V

SHEET 1 OF 1

PART NO 172746

REV

COPYRIGHT 2010 WINNEBAGO INDUSTRIES, INC.

10 730C

REF: 1 6/8/2010