



If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



Copyright © 2015 Winnebago Industries, Inc.








8	7	6
---	---	---


SEE DWG NO. 128783-01-000

2	1 No 188859	
		D
		C
hitor connection beta a bab		В
AL IS 0 FOR ELECTRICAL CALLOUTS SEE DWG NO. 121339-01-000	41Q SOFA/SLEEPER-ULTRALEATHER   265 CODES/STANDARDS-CSA/CMVSS   1B1 CODES/STANDARDS USA   1B1 265   FIRST USED   IDO NOT SCALE DRAWING   TITLE:   WIRING INSTL-BODY,110V   SHEET 2   PART NO   1 03-Feb-2015	*188859 *>









<b>)</b>	Γ	+	3