





DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.





CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.



- NOTES:
- 10 SEE GENERATOR INSTL FOR ADDITIONAL INFORMATION.
 - 9 WIRE ROUTED BELOW FLOOR.
 - 8 ALL GROUND WIRE TO BE COVERED WITH TUBING 8041-02-000.
 - 7 SEE WIRING INSTL TV-VCR, FRONT FOR ADDITIONAL INFORMATION.
 - 6 LOCATE RECEPTACLE ON REFRIGERATOR TIE DOWN BRACKET.
 - 5 NOT USED WITH 76C OR 1D5
 - 4 SEE ENT CTR INSTL-EXT FOR ADDITIONAL INFORMATION.
 - 3 WIRE ROUTED IN SIDEWALL.
 - 2 ROUTE WIRE THRU ROOF.
 - 1 ROUTE WIRE THRU FLOOR.




FOR ELECTRICAL TORQUE SPECIFICATIONS SEE DWG NO. 128783-01-000

FOR ELECTRICAL CALLOUTS SEE DWG NO. 121339-01-000

- 53D WTR HTR-6GAL/ELE/LP/MOTORAID
- 1D5 ENTERTAINMENT CTR/EXT W/CD
- 39A EXT RECEPTACLE DPLX 120 VAC
- 76C ENTERTAINMENT CTR/EXT CASSETTE
- 12D ELECTRICAL SYSTEM 30 AMP
- 265 CODES/STANDARDS-CSA/CMVSS
- 1B1 CODES/STANDARDS USA

FIRST USED		03 430V
DO NOT SCALE DRAWING		
TITLE:		WIRING INSTL-BODY, 110V
SHEET 2	PART NO	141666



DWG NO 141666


CLAMP
10495-01-000 (4)
SCREW
G67-10-12B (4)
REAR SLIDEOUT WIRE
CORD-FLEX
136151-03-017
(BRN)

110V WIRE
FROM RIGHT SIDE

CONNECTOR-WIRE, SOW
144283-01-000 (2)
SCREW
G39-06-24B (4)

CONNECTOR-WIRE, NM
144283-02-000 (2)
SCREW
G39-06-24B (4)

FOR
ELECTRICAL
CALLOUTS
SEE DWG NO.
121339-01-000



FIRST USED		03 430V
DO NOT SCALE DRAWING		
TITLE:		WIRING INSTL-BODY, 110V
SHEET 3	PART NO	141666

1 02/28/03