




DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.




CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.



- ⑥ CONNECT PURPLE-2 TO INVERTER WITH FEATURE (40B).
- ⑤ FOR USE WITH SHELLS ONLY.
- ④ SLIT AS NEEDED TO RUN WIRES.
- 3. WHERE WIRES PASS THROUGH HOLES IN STEEL AND ARE NOT OTHERWISE PROTECTED, USE GROMMET 92908-02-000.
- ② REMOVE VINYL FROM CUTOUT AT INSTALLATION.
- ① NOT USED WITH (20C) SOUND SYSTEM-DLX.


FOR
 DETAIL
 CALLOUTS
 SEE DWG NO.
 130375-01-000



NOTES:
 (3) CABLE ROUTED IN ROOF
 (2) NOT USED ON SHELL.
 (1) CABLE ASM MARKED WITH COLORED TAPE.

- (35P) VIDEO SELECTION SYSTEM
- (20F) DELUXE SOUND SYSTEM-WITHOUT
- (72H) VCR
- (42R) TV-25" COLOR
- (40F) INVERTER-DC/AC-130 WATT
- (40B) INVERTER-DC/AC. 300 WATT

TITLE		WIRING INSTL-TV/VCR,FRONT	
DD	NOT SCALE DRAWING	SIZ	NO
SHEET	6 OF 10	IE	NO 141308
		07/23/02	




VIEW JA-JA
(20C)

- NOTES:
- (2) CABLE ROUTED IN ROOF.
 - (1) CABLE ASM MARKED WITH COLORED TAPE.

(20C) SOUND SYS. DLX. W/O-SURROUND
 (35P) VIDEO SELECTION SYSTEM

TITLE		WIRING INSTL-TV/VCR,FRONT	
DD	NOT SCALE DRAWING	SHEET	7 OF 10
DATE	07/23/02	NO	141308



VIEW KA-KA
(25F) (20C)

- NOTES:
- (3) SUPPLIED WITH DVD PLAYER
 - (2) CABLE ROUTED IN ROOF.
 - (1) CABLE ASM MARKED WITH COLORED TAPE.

- (20C) SOUND SYS. DLX. W/O-SURROUND
- (25F) DIGITAL VIDEO DISC PLAYER
- (35P) VIDEO SELECTION SYSTEM

TITLE		WIRING INSTL-TV/VCR,FRONT	
DD	NOT SCALE DRAWING	SHEET	8 OF 10
DWG NO	141308	DATE	07/23/02