




Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.


## 


If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.











8	7	6	5	, 4	3	2	1
							[ <sup>™</sup> 151138
D							D
	BRACKET A	ANTENNA					
	GROUND	$\overline{\langle 1 \rangle}$			_		
				(480) D	DM - 1		
		=					
JP FRO	W WIRE ASM-ROOF		C	E - TAN			
	DETAIL AA						
С							> c
<b>→</b>						(ANT-2)/2/3/4	-
					(ANT-R) ID5		
					SEAL DETAIL AA		
R							R
В							В
							480 SATELLITE DISH & ELEV.SENSOR
5 NOT USED WITH 13	3).						IJB TV ANTENNA-OMNIDIRECTIONAL   ID5 ENTERTAINMENT CENTR/EXT W/CD
							265 CODES/STANDARDS-CSA/CMVSS
A AD RUBBER BUMPERS	TO ROOF UNDER EACH Down position.						(1B1) CODES/STANDARDS USA
LOCATE CLIP TO RET	AIN CABLE BUT NOT TO RESTRICT ANTENNA	۸.					FIRST USED
$\frac{2}{2}$ see drawing 76319-01-000 for istallation of tv antenna,							05 327L
1 WRAP BRACKET LEGS	AROUND ANTENNA BASE.						DO NOT SCALE DRAWING
NOTES:							WIRING INSTLBODY,12V SHEET 6 151138
8	7	6	5	4	3	2	l 3/10/2005