




DANGER


Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.





CAUTION


If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.

























WIRING DIAGRAM-IP, RIGHT
(WIRE ASM 145532 REV-D)



WIRING DIAGRAM-WIPER/WASHER
(WIRE ASM 145778-02 REV-D) (MMDC)



WIRING DIAGRAM-DOOR LOCK
(WIRE ASM 132267 REV-C)

2 SEE MANUFACTURERS DIAGRAM FOR
ADDITIONAL INFORMATION.

1. SPLICES ARE THEORETICAL AND MAY DIFFER IN THE HARNESS.

NOTES:

FIRST USED		05 S-SERIES	
		DO NOT SCALE DRAWING	
TITLE:			
WIRING DIAGRAM-AUTO			
SHEET 4		PART NO 148577	

8 7 6 5 4 3 2 1

DWG NO 148577

D

C

B


A

D


C

B

A



WIRING DIAGRAM-ADAPTER,SL IDEOUT
(WIRE ASM 149903-01 REV-A)



WIRING DIAGRAM-ADAPTER,SL IDEOUT
(WIRE ASM 149903-02 REV-A)


2 SEE MANUFACTURERS DIAGRAM FOR ADDITIONAL INFORMATION.

1. SPLICES ARE THEORETICAL AND MAY DIFFER IN THE HARNESS.

NOTES:

FIRST USED	05 S-SERIES	
TITLE	DO NOT SCALE DRAWING	
	WIRING DIAGRAM-AUTO	
SHEET 5	PART NO	148577

8 7 6 5 4 3 2 1



WIRING DIAGRAM-ADAPTER,SLIDEOUT
(WIRE ASM 149903-03 REV-A)

2 SEE MANUFACTURERS DIAGRAM FOR
ADDITIONAL INFORMATION.

1. SPLICES ARE THEORETICAL AND MAY
DIFFER IN THE HARNESS.

NOTES:

FIRST USED		05 S-SERIES	
		DO NOT SCALE DRAWING	
TITLE:		WIRING DIAGRAM-AUTO	
SHEET 6		PART NO	148577