

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.

	8		7		6	5	4	3		2	1
	DRAWING NO.	SHEET	SERIES				_	·			RELEASE A
	160329-01	1	200				<i>•</i>				REV ZONE REVISION RECORD DATE OF TR-ORIG
	160329-02	2	300					\geq			
	160329-03	З	500	4							
	160329-04	4	700	_							
	160329-05	5	D,E,F,G	-							D
	160329-06	6	M,P,R,S	_							
	160329-07	7	B-VAN								
	160329-08	8	500]_5		1					
с Т					ANTENNA-RADIO						C
В											Z65 CODES/STANDARDS-CSA/CMVSS IBI CODES/STANDARDS USA
A	AND SIZE. 3	5-08 IS ONLY 5-MODIFIED DR. 2007 CHASSIS (ITH CHASSIS, 1	AWING FOR HOLE LOCA DNLY. JSE SHORT ANTENNA O NTENNA ON 2007 CHAS	IN				I SPE(ELECTRICAL TORQUE CIFICATIONS EE DWG NO. 3783-01-000	FOR ELECTRICAL CALLOUTS EEE DWG NO. 1339-01-000	COPYRIGHT 2006 WINNEBAGO INDUSTRIES, INC. OFTR OFT
	8		7		6	5	1 4	3		2	REF: 1 2/25/2008













