




DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.



- (49B) BED-KING, MEMORY FOAM
- (49A) BED-KING, INNERSPRING
- (48B) BED-QUEEN, MEMORY FOAM
- (48A) BED-QUEEN, INNERSPRING
- (410) SOFA/SLEEPER-ULTRALEATHER HP
- (48D) BED-QUEEN, SLEEP NUMBER
- (49C) BED-KING, SLEEP NUMBER
- (1D3) ENTERTAIN CENTR/EXT TV-DVD
- (1EC) END TABLE CABINET
- (14C) FIREPLACE-ELECTRIC
- (265) CODES/STANDARDS - CSA/CMVSS
- (1B1) CODES/STANDARDS - USA

- NOTES:
- (6) WITHOUT (49A) OR (49B)
 - (5) WITHOUT (410)
 - (4) WIRE IN SIDEWALL.
 - (3) WIRE ROUTED IN ROOF.
 - (2) WIRE ROUTED IN SIDEWALL.
 - (1) ALL OUTLETS DOWN STREAM AND INCLUDING THIS OUTLET ARE GROUND GAULT INTERRUPT PROTECTED.
 - (8) WIRE DEAD ENDS AT RCP-BLANK #1 WITH (49A) OR (49B)
 - (7) CONNECTS TO 110V SLIDEOUT CONNECTOR WITHOUT (48D) OR (49C)

WINNEBAGO		COPYRIGHT 2010 WINNEBAGO INDUSTRIES, INC.	
DFTR	ORIG. DATE		
CHKR	ALL DIMENSIONS ARE IN MILLIMETERS		
P.E.			
M.E.	FIRST USED		
DSNR	10 P40L		
UNSPECIFIED TOLERANCES ARE:		MATERIAL:	
WHOLE DIM (X)	:		
ONE-PLACE (X.X)	:		
TWO-PLACE (X.XX)	:		
ANGLE	:		
THIRD ANGLE PROJECTION			
DO NOT SCALE DRAWING			
TITLE: WIRING DIAGRAM-BODY, 110V			
SHEET 1 of 1	PART NO	171527	REV
REF:	1/2/23/2010		