



If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.




Copyright © 2014 Winnebago Industries, Inc.





8	7	6
---	---	---



MOUNT BRACKETS TO SEAT SWIVEL MECHANISM BY LOOSENING BOLTS ON BOTH TOP AND BOTTOM OF MECHANISM.

NOTES:



NO 183312

WIR IP GX	RE ASM- MAIN		D
COM	DETAIL CB		C
			B
NS	IB1 COD 1B1 26 FIRST USED FIRST USED TRICAL LOUTS TITLE:	ES/STANDARDS-CSA/CMVSS ES/STANDARDS USA 55 <b>14 623L</b> NOT SCALE DRAWING NG INSTL-CHASSIS PART NO 183312	*183312