


If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.




Copyright © 2014 Winnebago Industries, Inc.




Ο		


2			1		833	27	
	REV ZONE		ON RECORD				
							D
A A PUR-2)							С
CH WIRE #3 (PUR) 401 WIRE #4 (PUR-2) 5 E #2 CTORS	(401)	INVERTER-	-DC/AC,	1000 V	VATT		B
	78J 265 1B1 1B1	ELECTRICA CODES/STAI CODES/STAI	NDARDS-	CSA/CI USA	MVSS		
L S D ELECTRICAL CALLOUTS SEE DWG NO. 121339-01-000	DFTR CHKR P.E. M.E. DSNR UNSPECIFIE WHOLE DIN ONE-PLACE TWO-PLACE ANGLE THIRD ANGI PROJECTION DO NOT S TITLE:	$ \begin{array}{cccccccccccccccccccccccccccccccccccc$	ORIG. I ORIG. I ALL IN FIRST U T MATERIAL:		GUIDELIN (,110\	BARE BARE BARE BARE BARE BARE BARE BARE	*183334 *>




8 7 6

2 1 ^{DWG} 183334	
	D
	С
	-
2 2 3	B
41Q SOFA/SLEEPER-ULTRALEATHER 265 CODES/STANDARDS-CSA/CMVSS 1B1 CODES/STANDARDS USA 1B1 265 1B1 265 1B1 265 FREST USED FREST USED FREST USED FREST USED FREST USED FREST USED FREST USED FREST USED DO NOT SCALE DRAWING TITLE: WIRING INSTL-BODY,110V SHEET 2 PART NO 183334 PEV 1 26-Feb-2014	*183334 *>







	4	3