



If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.


Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



Copyright © 2015 Winnebago Industries, Inc.







	TOOLOL	-
	WIRE ASM- IP MAIN GX CHIME GND	D
	DETAIL CB 3	С
		•
		В
AL NS	265 CODES/STANDARDS-CSA/CMVSS 1B1 CODES/STANDARDS USA 1B1 265 IB1 265 I	190252 * ^{>}
	SHEET 3 PART NO 190252 REV 2 1 28-Jan-2015	*
1		

^{DWG} 190252

2