




— LABEL-CIRCUIT BREAKER
93236-53-000

— PLATE-CIRCUIT,BREAKER
000019322 / 313830-01-CHT
SCREW
G39-08-089 (2)

- 3 SEE COMPONENT DRAWING FOR TORQUE SPECIFICATIONS.
- 2 USE THE LONGER SCREW TO PROPERLY ATTACH BREAKER TO BUSS BAR.
- 1 REPLACE EXISTING SCREW TO PROPERLY ATTACH BREAKER TO BUSS BAR.

NOTES:


265 CODES/STANDARDS-CSA/CMVSS

1B1 CODES/STANDARDS USA

1B1 265




COPYRIGHT 2024 WINNEBAGO INDUSTRIES, INC

DSNR:		COPYRIGHT 2024 WINNEBAGO INDUSTRIES, INC.	
DFTT:		ALL DIMENSIONS ARE IN MILLIMETERS 	
UNSPECIFIED TOLERANCES:		MATERIAL:	
WHOLE DIM (X)	± 3		
ONE-PLACE (X.X)	± 1.5		
TWO-PLACE (X.XX)	± 0.50		
ANGLE	± 1°		
REFER TO ES0018 FOR FASTENER TIGHTENING GUIDELINES		WEIGHT: (LBS)	FIRST USED:
			22 E-SER
DESCRIPTION:			
CHASSIS ELECTRICAL BOX ASM			
SHEET:	ITEM/PART NO:		REV
1 OF 2	000225493 / 34397301000		

	INDICATES A CRITICAL CHARACTERISTIC. ENSURE PROPER PROCEDURES ARE FOLLOWED.
	INDICATES A SIGNIFICANT CHARACTERISTIC. ENSURE PROPER PROCEDURES ARE FOLLOWED.
	INDICATES A KEY CHARACTERISTIC. ENSURE PROPER PROCEDURES ARE FOLLOWED.

FOR ELECTRICAL
TORQUE
SPECIFICATIONS
SEE DWG NO.
128783-01-000

	FOR ELECTRICAL CALLOUTS SEE DWG 000228177 344479-01-000
---	---



- 9 SEE COMPONENT DRAWING FOR TORQUE SPECIFICATIONS.
- 8 SEE WIRING INSTL-CHASSIS FOR ADDITIONAL IFORMATION.
- 7 SEE BATTERY INSTL FOR ADDITIONAL INFORMATION.
- 6 SECURE WITH SOLENOID MOUNTING SCREW.
- 5 WIRE MARKED WITH PURPLE TAPE.
- 4 WIRE MARKED WITH YELLOW TAPE.
- 3 WIRE MARKED WITH 2 WRAPS OF YELLOW TAPE.
- 2 WIRE MARKED WITH RED TAPE.

1. SECURE CONDUIT 41953, TAB AS REQUIRED,
OVER ALL WIRES IN CONTACT WITH SHARP EDGES.

NOTES: