




DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.





CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.











WIRING DIAGRAM-IP.MAIN
(WIRE ASM 126348)


99 F & G SERIES

TITLE	WIRING DIAGRAM-AUTO.FL
TO SHEET 3 OF 12	131000







WIRING DIAGRAM-IP, CENTER
(WIRE ASM 113469)
(W/C/D PLAYER)




WIRING DIAGRAM-REMOTE MIRRORS
(WITH REMOTE MIRROR/MIRRORS
(WIRE ASM 126392)



WIRING DIAGRAM-IP, BAT DISCONNECT
(WITH BATTERY DISCONNECT)
(WIRE ASM 108306)



WIRING DIAGRAM-IP, REAR AUTO HEATER
(WITH REAR AUTO HEATER)
(WIRE ASM 108303)











WIRING DIAGRAM-CLEARANCE LAMPS
(WIRE ASM 126486)


SEE SHT 1, 2, AND 3 FOR ADDITIONAL INFORMATION.


NOTES:


99 F.G-SERIES
WIRING DIAGRAM-AUTO
131000





③ SEE WIRING DIAGRAM-BODY FOR ADDITIONAL INFORMATION.
② SEE MANUFACTURER'S DIAGRAM FOR ADDITIONAL INFORMATION.
① SEE SHT 1 FOR ADDITIONAL INFORMATION.



















5. WITHOUT DELUXE SOUND.
4. WITH DELUXE SOUND.
3. SEE MANUFACTURER'S DIAGRAM FOR ADDITIONAL INFORMATION.
2. SUPPLIED WITH CHASSIS.
1. SEE WIRING DIAGRAM-BODY FOR ADDITIONAL INFORMATION.











SEE MANUFACTURER'S DIAGRAM FOR ADDITIONAL INFORMATION.

NOTES:

99.5 F & G SERIES

WIRING DIAGRAM-BODY, 12V
SHEET 12 OF 14

131000



SEE MANUFACTURER'S DIAGRAM FOR ADDITIONAL INFORMATION.

SEE SHT'S 8, 9, 10 FOR ADDITIONAL INFORMATION.

NOTES:

99.5 F & G SERIES

TITLE: WIRING DIAGRAM-BODY, I2V
SHEET 13 OF 14
DATE: 1.6
REV: 131000

