



DANGER




Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.



CAUTION

If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.

DWG	MODEL
131908-01	WIN
131908-02	ITA



- NOTES:
1. ALL WIRES TO BE CLAMPED WITH CLAMP 10495-01-000 OR CLIP 80734-02-000 EVERY 700. USE SCREW G67-10-12B UNLESS OTHERWISE SPECIFIED.
 2. CLAMP TO FLOOR SUPPORT TUBES AS NECESSARY WITH CLAMP 10497-01-000.
 3. WIRES THAT REST ON WIRE TRAYS ARE TO BE TIES DOWN WITH WIRE TIE 8343-02-000.

FOR ELECTRICAL TORQUE SPECIFICATIONS SEE DWG NO. 128783-01-000

FOR ELECTRICAL CALLOUTS SEE DWG NO. 121339-01-000

64R EXTERIOR WASH STATION

265 CODES/STANDARDS-CSA/CMVSS

1B1 CODES STANDARDS/USA

64R 1B1 265


WINNEBAGO 00 L36L.P


DATE	REVISION	DESCRIPTION
11/13/98	1	INITIAL PRODUCTION




WIRING INSTL-BODY.12V(BL)

131908


REF: 130345-K 1








CIRCUIT BREAKER (FRONT VIEW)




CIRCUIT BREAKER (BACK VIEW)



530	WINTERIZING KIT
290	SOLAR PANEL - 10 WATT
265	CODES/STANDARDS-CSA/CMVSS
181	CODES STANDARDS/USA
00	L36L,P
265	181
WIRING INSTL-BODY,12V(BP)	
SHEET 4 OF 5	
131908	

FOR ELECTRICAL
TORQUE
SPECIFICATIONS
SEE DWG NO
128783-01-000



- 8 SEE DWG 76319-01-000 FOR INSTALLATION OF TV ANTENNA.
- 7 ADD RUBBER BUMPERS TO ROOF UNDER EACH END OF ANTENNA TO PREVENT CONTACT WITH ROOF.
- 6 SEE WIRING INSTL-BODY, 110V FOR ADDITIONAL INFORMATION.
- 5 INSTALL WITH WIRES TOWARDS ROOF.
- 4 FASTEN TO VENT.
- 3 WRAP BRACKET LEGS AROUND ANTENNA BASE.
- 2 CONNECTOR-PLUG, TRAILER (113589-01-000) TO BE SUPPLIED LOOSE IN COACH WITH TRAILER TOW PACKAGE.
- 1 TAPE BRANCH BACK ALONG WIRE ASM WITH TAPE 8363-01-000.

NOTES: