




DANGER

Danger of electrical shock, burns or death. Always remove all power sources before attempting any repair, service or diagnostic work. Power can be present from shore power, generator, inverter or battery. All power sources must be disabled and secured before performing any service.






CAUTION






If you lack the skills, tools or equipment to perform diagnostic or repair work leave such work to an authorized Winnebago Industries dealer or other qualified shop.



CENTRAL AIR UNIT
 (LOCATED IN RIGHT REAR COMPARTMENT BELOW FLOOR)




INVERTER BREAKER PANEL







- ④ 2IN DISHWASHER-UNDER COUNTER BUILT-IN.
- ③ WIRE ROUTED IN ROOF.
- ② WIRE ROUTED IN SIDEWALL.
- ① PROTECTED BY GFI RECP.

78J ELECTRICAL SYS 50-AMP













WINNEBAGO		99 M39Y
DATE	UNDESIGNED TOLERANCES ARE:	MATERIAL
DATE	WHOLE DIM IN	
DATE	ONE-PLACE IN .01	
DATE	TWO-PLACE IN .005	
DATE	THREE-PLACE IN .002	
DATE	FOUR-PLACE IN .001	
DATE	FIVE-PLACE IN .0005	
DATE	SIX-PLACE IN .0002	
DATE	SEVEN-PLACE IN .0001	
DATE	EIGHT-PLACE IN .00005	
DATE	NINE-PLACE IN .00002	
DATE	TEN-PLACE IN .00001	
DATE	UNDESIGNED TOLERANCES ARE:	MATERIAL
DATE	WHOLE DIM IN	
DATE	ONE-PLACE IN .01	
DATE	TWO-PLACE IN .005	
DATE	THREE-PLACE IN .002	
DATE	FOUR-PLACE IN .001	
DATE	FIVE-PLACE IN .0005	
DATE	SIX-PLACE IN .0002	
DATE	SEVEN-PLACE IN .0001	
DATE	EIGHT-PLACE IN .00005	
DATE	NINE-PLACE IN .00002	
DATE	TEN-PLACE IN .00001	
DATE	UNDESIGNED TOLERANCES ARE:	MATERIAL
DATE	WHOLE DIM IN	
DATE	ONE-PLACE IN .01	
DATE	TWO-PLACE IN .005	
DATE	THREE-PLACE IN .002	
DATE	FOUR-PLACE IN .001	
DATE	FIVE-PLACE IN .0005	
DATE	SIX-PLACE IN .0002	
DATE	SEVEN-PLACE IN .0001	
DATE	EIGHT-PLACE IN .00005	
DATE	NINE-PLACE IN .00002	
DATE	TEN-PLACE IN .00001	



CENTRAL AIR UNIT
(LOCATED IN RIGHT REAR COMPARTMENT BELOW FLOOR)



INVERTER BREAKER PANEL



- (4) 54E WASHER/DRYER COMBINATION.
- (3) WIRE ROUTED IN ROOF.
- (2) WIRE ROUTED IN SIDEWALL.
- (1) PROTECTED BY GFI RECP.

99 M39Y
50 AMP CAN